

TSS Report



Report Template Version: 1.1

Created On: 08/07/2012 16:05:36
Center: District 9
Filter Parameters Selected: [From Date Time]: 01/09/2012 00:00, [To Date Time]: 01/10/2012 00:00
Period: 01/09/2012 [00:00:00] to 01/10/2012 [00:00:00]

Device Number	Device Location	Device Type	Manufacturer
AVI_Tc_Lab:tss:detector	ITS Lab 192.168.11.73: addr 514	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
AVI_Tc_Springhill:tss:detector	Springhill Mast Arm	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
IVV_LPR2:tss:detector	Clay Workstation 8051	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%


Device Number	Device Location	Device Type	Manufacturer
IVV_LPR:tss:detector	Clay Workstation 8.201:8050	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
LPR_TERL:tss:detector	Springhill Road	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RMS-D9-T2:tss:detector		detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RSE_OT:tss:detector	Convention center	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:13:19	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:50	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:25:42	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:25:57		
offline	01/09/2012 08:26:17	The driver did not receive a detector update.	
offline	01/09/2012 08:28:12	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:28:17		
offline	01/09/2012 08:28:37	The driver did not receive a detector update.	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RSE_Sim2:tss:detector	RSE_Sim2	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:13:19	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:50	The driver has changed the OpStatus for this device.	



TSS Report



Report Template Version: 1.1

offline	01/09/2012 08:25:42	The driver has changed the OpStatus for this device.
online	01/09/2012 08:25:57	
offline	01/09/2012 08:26:17	The driver did not receive a detector update.
offline	01/09/2012 08:28:12	The driver has changed the OpStatus for this device.
online	01/09/2012 08:28:17	
offline	01/09/2012 08:28:37	The driver did not receive a detector update.

Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RSE_Sim3:tss:detector	Rse_Sim3	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:13:18	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:49	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:25:41	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:25:57		
offline	01/09/2012 08:26:17	The driver did not receive a detector update.	
offline	01/09/2012 08:28:11	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:28:17		
offline	01/09/2012 08:28:37	The driver did not receive a detector update.	


Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RSE_Sim4:tss:detector	the 4th RSE	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:13:19	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:50	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:25:42	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:25:57		
offline	01/09/2012 08:26:17	The driver did not receive a detector update.	
offline	01/09/2012 08:28:12	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:28:17		
offline	01/09/2012 08:28:37	The driver did not receive a detector update.	

Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RSE_Sim:tss:detector	RSE_Sim	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:13:18	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:13:19	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:49	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:15:50	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:25:41	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:25:42	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:25:57		
offline	01/09/2012 08:26:17	The driver did not receive a detector update.	
offline	01/09/2012 08:28:11	The driver has changed the OpStatus for this device.	
offline	01/09/2012 08:28:12	The driver has changed the OpStatus for this device.	
online	01/09/2012 08:28:17		
offline	01/09/2012 08:28:37	The driver did not receive a detector update.	

Uptime Percentage: 0.0%



TSS Report



Report Template Version: 1.1

Device Number	Device Location	Device Type	Manufacturer
RTMS-01:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:18	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-02:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:20	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-03:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-04:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%


Device Number	Device Location	Device Type	Manufacturer
RTMS-05:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-06:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-07:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:20	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-08:tss:detector	1	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-09:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%



TSS Report



Report Template Version: 1.1

Device Number	Device Location	Device Type	Manufacturer
RTMS-10:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-11:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:19	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-12:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:20	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-13:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:20	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-14:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 07:38:20	The driver did not receive a detector update.	
			Uptime Percentage: 31.8%

Device Number	Device Location	Device Type	Manufacturer
RTMS-IVV:tss:detector	I-10 Strip	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
RTMS_G4:tss:detector	Not Really Offset from Springhill Road	detector	
State	Up/Down Time	Failure Reason	
offline	01/09/2012 08:28:21	The driver did not receive a detector update.	
			Uptime Percentage: 0.0%

Device Number	Device Location	Device Type	Manufacturer
SS105_I95_MM14:tss:detector	Jacksonville MVDS Test Site	detector	
State	Up/Down Time	Failure Reason	
			Uptime Percentage: 0.0%