



Created On: Center: Filter Paramete	ers Selected:	08/01/2012 11:25:11 District 5 [From Date Time]: 02/01/2012	00:00, [To Date Time]: 02/01/20	012 10:00			
Period:		02/01/2012 [00:00:00] to 02/01/2012 [10:00:00]					
Device Numbe	er	Device Location	Device Type	Manufacturer			
Detour 5A W O	F US 1 EB	SR-5A EB W of US-1	dms	DakTronix			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	100.0%		
Device Numbe	er	Device Location	Device Type	Manufacturer			
Detour Bellevue @Williamson EB	e @Williamson	Bellevue Ave EB at Williamso	on dms	FDS			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	0.0%		
Device Numbe		Device Location	Device Type	Manufacturer			
Detour Bellevue WB	e @Williamson	Bellevue Ave WB at Williams	on dms	FDS			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	0.0%		
Device Number Detour Beville @ Williamson EB		Device Location Beville Rd EB at Williamson	dms	Manufacturer FDS			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	0.0%		
Device Numbe	ər	Device Location	Device Type	Manufacturer			
Detour Beville (WB	@ Williamson	Beville Rd WB at Williamson	dms	FDS			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	100.0%		
Device Number		Device Location	Device Type	Manufacturer			
Detour Beville (MorrisEB	@Clyde	Beville Rd EB at Clyde Morris	s dms	FDS			
	State	Up/Down Time	Failure Reason				
				Uptime Percentage:	0.0%		





				Report remplate version	JII. 1.2
Device Numbe	er	Device Location	Device Type	Manufacturer	
Detour Beville (MorrisWB	@Clyde	Beville Rd WB at Clyde Morri	s dms	FDS	
	State	Up/Down Time	Failure Reason		
	State	op/Down Time	Failure Reason	Uptime Percentage:	0.0%
Device North		Device Legation			
Device Number Detour CR 502		Device Location CR-502 EB W of I-95	Device Type dms	Manufacturer DakTronix	
	W OI 1-33 ED		uns	Daktionix	
	State	Up/Down Time	Failure Reason		
	Otale	op/Down nine		Uptime Percentage:	100.0%
Device Numbe	۶r	Device Location	Device Type	Manufacturer	
Detour CR 502		CR-502 EB W of US-1	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
		-		Uptime Percentage:	100.0%
Device Numbe	er	Device Location	Device Type	Manufacturer	
Detour CR 509	E of Suntree	CR-509 WB E of Suntree Blv	d dms	DakTronix	
WB					
	.				
	State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
					100.078
Device Number Detour CR 509		Device Location CR-509 SB N of CR-516	Device Type dms	Manufacturer DakTronix	
SB	N OF CK 510	CK-309 3B N 01 CK-310	uns	Daktionix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numbe		Device Location	Device Type	Manufacturer	
Detour CR 509 SB	N of SR 518	CR-509 SB N of SR-518	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numbe		Device Location	Device Type	Manufacturer	
Detour CR 509 NB	S of US 192	CR-509 NB S of US-192	dms	DakTronix	
	State	Up/Down Time	Failure Reason	Hading Deve at	400.00/
				Uptime Percentage:	100.0%





Device Number	Device Location	Device Type	Manufacturer	
Detour CR 509 W of Suntree EB	CR-509 EB W of Suntree Blvd	dms	DakTronix	
State	Up/Down Time Fa	ilure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour CR 516 E of CR 509 WB	CR-516 WB E of CR-509	dms	DakTronix	
State	Up/Down Time Fa	illure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour CR 516 W of CR 507 EB	CR-516 EB W of CR-507	dms	DakTronix	
State	Up/Down Time Fa	illure Reason		
	•		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Clyde Morris @ US 92 NB	Clyde Morris Blvd NB at US-92	dms	FDS	
State	Up/Down Time Fa	ilure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Clyde Morris @ US 92 SB	Clyde Morris Blvd SB at US-92	dms	FDS	
State	Up/Down Time Fa	ilure Reason		
	•		Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Clyde Morris @BevilleNB	Clyde Morris Blvd NB atBeville	dms	FDS	
State	Up/Down Time Fa	ulure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Clyde Morris @BevilleSB	Clyde Morris Blvd SB atBeville	dms	FDS	
State	Up/Down Time Fa	illure Reason		





Device Number	Device Location	Device Type	Manufacturer	
Detour Cox Rd S of SR 520 NB	Cox Rd NB S of SR-520	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Cox Rd S of SR 524 NB	Cox Rd NB S of SR-524	dms	DakTronix	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Industry N of SR 524 SB	Industry Rd SB N of SR-52	4 dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour John Rodes N US192 SB	John Rodes Blvd SB N US-	.192 dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour John Rodes S SR518 NB	John Rodes Blvd NB S SR-		DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Kepler @ SR 44 N	Kepler Rd NB at SR-44	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Kepler @ SR 44 S	Kepler Rd SB at SR-44	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%





			Report Template Versio	/11. 1.2
Device Number	Device Location	Device Type	Manufacturer	
Detour Kepler @ US-92 N	Kepler Rd NB at US-92	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour LPGA @ Williamson EB	LPGA Blvd EB at Williamson	dms	FDS	
State	Up/Down Time	Failure Reason		0.00/
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour LPGA @ Williamson WB	LPGA Blvd WB at Williamsor	ı dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Nova @ US 1 NB	Nova Rd NB at US-1	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Nova EB	SR-40 EB at Nova Rd	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Nova NB	Nova Rd NB at SR-40	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Nova SB	Nova Rd SB at SR-40	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Nova WB	SR-40 WB at Nova Rd	dms	FDS	





Uptime Percentage:	0.0%
--------------------	------

			optime r ercentage.	0.070
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Williamson EB	SR-40 EB at Williamson Blv		FDS	
State	Up/Down Time	Failure Reason		
State	Op/Down Time	Failure Reason	Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 @ Williamson WB	SR-40 WB at Williamson Bl		FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 40 West of I95 EB	SR-40 EB W of I-95	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 405 S of SR 50 NB	SR-405 NB S of SR-50	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 405 W of SR 407 EB	SR-405 EB W of SR-407	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 405 W of Tico Rd EB	SR-405 EB W of Tico Rd	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 406 W of US 1 EB	SR-406 EB W of US-1	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%





Report Template Version: 1.2

Device Number	Device Location	Device Type	Manufacturer	
Detour SR 407 S of SR 405 NB	SR-407 NB S of SR-405	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 415 N of SR 44 SB	SR-415 SB N of SR-44	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 415 S of SR 421 NB	SR-415 NB S of SR-421	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 421 E of SR 415 WB	SR-421 WB E of SR-415	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 421 W of I-95 EB	SR-421 EB W of I-95	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 421 W of I-95 WB	SR-421 WB W of I-95	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 44 @ Kepler EB	SR-44 EB at Kepler Rd	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%





Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 @ k	Kepler WB	SR-44 WB at Kepler Rd	dms	FDS	
s	tate	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 @ L	JS 1 EB	SR-44 EB at US-1	dms	DakTronix	
<u>s</u>	tate	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 E of	f I-95 WB	SR-44 WB E of I-95	dms	DakTronix	
<u>s</u>	tate	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 E of	f SR 415 WB	SR-44 WB E of SR-415	dms	DakTronix	
S	tate	Up/Down Time	Failure Reason		
_				Uptime Percentage:	0.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 W o	of I-95 EB	SR-44 EB W of I-95	dms	DakTronix	
s	tate	Up/Down Time	Failure Reason		
<u> </u>				Uptime Percentage:	0.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 44 W o	f US 1 EB	SR-44 EB W of US-1	dms	DakTronix	
	4-4-		Failure Reason		
5	tate	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
				· · ·	100.0 /8
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 442 W	of US 1 EB	SR-442 EB W of US-1	dms	DakTronix	
<u>s</u>	tate	Up/Down Time	Failure Reason		400.00/
				Uptime Percentage:	100.0%
Device Number	/	Device Location	Device Type	Manufacturer	
Detour SR 46 W o	of I-95 EB	SR-46 EB W of I-95	dms	DakTronix	
-	tate	Up/Down Time	Failure Reason		
<u>s</u>	late			Uptime Percentage:	100.0%





Device Number		Device Location	Device Type	Manufacturer	
Detour SR 46 W		SR-46 EB W of US-1	dms	DakTronix	
:	State	Up/Down Time	Failure Reason		
-		•		Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 50 E c	of I-95 WB	SR-50 WB E of I-95	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
_				Uptime Percentage:	0.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 50 Just E of I-95 WB	st E of I-95	SR-50 WB at I-95	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Number	(1.45.55	Device Location	Device Type	Manufacturer	
Detour SR 50 W	of I-95 EB	SR-50 EB W of I-95	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 50 W	of SR 405 EB	SR-50 EB W of SR-405	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 507 N SB	of SR 514	SR-507 SB N of SR-514	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour SR 507 S NB	of CR 516	SR-507 NB S of CR-516	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
	State	op/Down Time			





Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 514 EB	W of SR 507	SR-514 EB W of SR-507	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 518 EB	3 W John Rodes	SR-518 EB W of John Rode	es Blvd dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 518 W of CR 509 EB		SR-518 EB W of CR-509	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 519 S of SR 520 NB	9 S of SR 520	SR-519 NB S of SR-520	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 520 EB) W of Cox Rd	SR-520 EB W of Cox Rd	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour SR 520 EB) W of SR 519	SR-520 EB W of SR-519	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb		Device Location	Device Type	Manufacturer	
Detour SR 524 WB	E of Cox Rd	SR-524 WB E of Cox Rd	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
		-		Uptime Percentage:	100.0%





Device Number	Device Location	Device Type	Manufacturer	
Detour SR 524 W of Cox Rd EB	SR-524 EB W of Cox Rd	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 524 W of Industry EB	SR-524 EB W of Industry Rd	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR 528 W of Industry EB	SR-528 EB W of Industry Rd	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR405 W of Singleton EB	SR-405 EB W of Singleton Ave	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR406 E of US 1 WB	SR-406 WB E of US-1	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour SR406 W of Singleton EB	SR-406 EB W of Singleton Ave	dms	DakTronix	
State	Up/Down Time Fa	ailure Reason		
			Uptime Percentage:	100.0%
			Manufacturer	
Device Number	Device Location	Device Type		
Device Number Detour Singleton N of SR405 SB	Device Location Singleton Ave SB N of SR-405	dms	DakTronix	
Detour Singleton N of SR405	Singleton Ave SB N of SR-405			





			Report Template Versit	
Device Number	Device Location	Device Type	Manufacturer	
Detour Singleton S of SR406 NB	Singleton Ave NB S of SR-4	06 dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Suntree E of CR 509 WB	Suntree Blvd WB E of CR-5	09 dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Suntree W of CR 509 EB	Suntree Blvd EB W of CR-5		DakTronix	
State	Up/Down Time	Failure Reason	Uptime Percentage:	0.0%
				0.0 /6
Device Number Detour US 1 N of 5A SB	Device Location US-1 SB N of SR-5A	Device Type dms	Manufacturer DakTronix	
Delour US I IN OF SA SB	03-1 3B N 01 3R-3A	uns	Dak HOHIX	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour US 1 @ Nova NB	US-1 NB at Nova Rd	dms	FDS	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour US 1 @ Nova SB	US-1 SB at Nova Rd	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour US 1 East of I95 NB	US-1 NB E of I-95	dms	FDS	
State	Up/Down Time	Failure Reason		
	-		Uptime Percentage:	0.0%
			Optime Percentage:	0.07





Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type dms Failure Reason Failure Reason Failure Reason Device Type dms Failure Reason Device Type dms	Device Location US-1 SB N of SR-442 Up/Down Time Device Location US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528 Up/Down Time	Device Number Detour US 1 N of SR 442 SB State Device Number Detour US 1 N of SR 46 SB State Device Number Detour US 1 N of SR 528 SB
Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer 100.0% DakTronix 100.0% Uptime Percentage: 100.0% DakTronix 100.0%	Failure Reason Device Type dms Failure Reason Device Type dms Failure Reason Device Type dms Device Type dms Device Type dms	Up/Down Time Device Location US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	State Device Number Detour US 1 N of SR 46 SB State Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type dms Failure Reason Device Type	Device Location US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	Device Number Detour US 1 N of SR 46 SB State Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type dms Failure Reason Device Type	Device Location US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	Device Number Detour US 1 N of SR 46 SB State Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type dms Failure Reason Device Type	Device Location US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	Device Number Detour US 1 N of SR 46 SB State Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	dms Failure Reason Device Type dms Failure Reason Device Type	US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	Detour US 1 N of SR 46 SB State Device Number
DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	dms Failure Reason Device Type dms Failure Reason Device Type	US-1 SB N of SR-46 Up/Down Time Device Location US-1 SB N of SR-528	Detour US 1 N of SR 46 SB <u>State</u> Device Number
Uptime Percentage: 100.0% Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix DakTronix DakTronix	Device Type dms Failure Reason Device Type	Up/Down Time Device Location US-1 SB N of SR-528	State Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type	Device Location US-1 SB N of SR-528	Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	Device Type dms Failure Reason Device Type	Device Location US-1 SB N of SR-528	Device Number
Manufacturer DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	dms Failure Reason Device Type	US-1 SB N of SR-528	
DakTronix Uptime Percentage: 100.0% Manufacturer DakTronix	dms Failure Reason Device Type	US-1 SB N of SR-528	
Uptime Percentage: 100.0% Manufacturer DakTronix	Failure Reason Device Type		Detour US 1 N of SR 528 SB
Manufacturer DakTronix	Device Type	Up/Down Time	
Manufacturer DakTronix	Device Type	Up/Down Time	
Manufacturer DakTronix			State
DakTronix			
	dms	Device Location	Device Number
Untimo Dorsentoros - 400.00		US-1 SB N of Suntree Blvd	Detour US 1 N of Suntree SB
Untimo Doscentosos - 400.00			
Lintima Davaartaga. 400.00	Failure Reason	Up/Down Time	State
UDUME Percentade: 100.0%			
· · · · ·		Device Location	Device Number
Manufacturer DakTronix	Device Type dms	US-1 NB S of SR-44	Device Number Detour US 1 S OF SR 44 NB
Baktronix	and		
			•
	Failure Reason	Up/Down Time	State
Uptime Percentage: 100.0%			
Manufacturer	Device Type	Device Location	Device Number
DakTronix	dms	US-1 NB S of CR-502	Detour US 1 S of CR 502 NB
	Failure Reason	Up/Down Time	State
Uptime Percentage: 100.0%			
Manufacturer	Device Type	Device Location	Device Number
DakTronix	dms	US-1 NB S of SR-405	Detour US 1 S of SR 405 NB
	Failure Reason	Up/Down Time	State
Uptime Percentage: 100.0%			
	Dovice Ture	Dovice Location	Dovice Number
Durrona	anio		
Uptime Percentage: 100.0%	Failure Reason	Up/Down Time	State
Uptime Percentage: 100.0%			
Manufacturer DakTronix	Failure Reason Device Type dms Failure Reason	Up/Down Time Device Location US-1 NB S of SR-442 Up/Down Time	State Device Number Detour US 1 S of SR 442 NB State





	-				
Device Number		Device Location	Device Type	Manufacturer	
Detour US 1 S of	SR 46 NB	US-1 NB S of SR-46	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
_				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 1 W of	195 SB	US-1 SB W of I-95	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 192 E EB	John Rodes	US-192 EB E John Rodes Bl	vd dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 192 E WB	of CR 509	US-192 WB E of CR-509	dms	DakTronix	
5	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 192 E WB	of Simon Rd	US-192 WB E of Simon Rd	dms	DakTronix	
S	State	Up/Down Time	Failure Reason		
-				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 192 W EB	of CR 509	US-192 EB W of CR-509	dms	DakTronix	
s	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Number		Device Location	Device Type	Manufacturer	
Detour US 92 @ I	Kepler WB	US-92 WB at Kepler Rd	dms	FDS	
<u>s</u>	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%





Device Numb		Device Location	Device Type	Manufacturer	
Detour US 92@	D LPGA EB	US-92 EB at LPGA Blvd	dms	Vultron	
	State	Up/Down Time	Failure Reason		
		•		Uptime Percentage:	0.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour US 92@	D LPGA SB	LPGA Blvd SB at US-92	dms	FDS	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour US 92@	D LPGA WB	US-92 WB at LPGA Blvd	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
Detour US-92 (EB	@ Clyde Morris	US-92 EB at Clyde Morris E	Blvd dms	FDS	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
		Device Location	Device Type	Manufacturer	
Detour US-92	er @ Clyde Morris	Device Location US-92 WB at Clyde Morris I		Manufacturer FDS	
Detour US-92					
Detour US-92	@ Clyde Morris	US-92 WB at Clyde Morris I	Blvd dms		0.0%
Detour US-92 (WB	@ Clyde Morris	US-92 WB at Clyde Morris I	Blvd dms	FDS	0.0%
Detour US-92 (WB Device Numb Detour US-92 (@ Clyde Morris State er	US-92 WB at Clyde Morris I Up/Down Time	Blvd dms Failure Reason Device Type	FDS Uptime Percentage:	0.0%
Detour US-92 (WB Device Numb Detour US-92 (@ Clyde Morris State er	US-92 WB at Clyde Morris I Up/Down Time Device Location	Blvd dms Failure Reason Device Type	FDS Uptime Percentage: Manufacturer FDS	
Detour US-92 (WB Device Numb Detour US-92 (<pre>@ Clyde Morris State er @ Williamson</pre>	US-92 WB at Clyde Morris I Up/Down Time Device Location US-92 EB at Williamson Bly	Blvd dms Failure Reason Device Type rd dms	FDS Uptime Percentage: Manufacturer	0.0%
Detour US-92 (WB Device Numb Detour US-92 (EB Device Numb	<pre>@ Clyde Morris State er @ Williamson State er</pre>	US-92 WB at Clyde Morris I Up/Down Time Device Location US-92 EB at Williamson Bly Up/Down Time Device Location	Blvd dms Failure Reason Device Type dms Failure Reason Device Type	FDS Uptime Percentage: Manufacturer FDS Uptime Percentage: Manufacturer	
Detour US-92 (WB Detour US-92 (EB Device Numb Detour US-92 (<pre>@ Clyde Morris State er @ Williamson State er</pre>	US-92 WB at Clyde Morris I Up/Down Time Device Location US-92 EB at Williamson Bly Up/Down Time	Blvd dms Failure Reason Device Type dms Failure Reason Device Type	FDS Uptime Percentage: Manufacturer FDS Uptime Percentage:	
Device Numb Detour US-92 (WB Device Numb Detour US-92 (EB Device Numb Detour US-92 (WB	<pre>@ Clyde Morris State er @ Williamson State er</pre>	US-92 WB at Clyde Morris I Up/Down Time Device Location US-92 EB at Williamson Bly Up/Down Time Device Location	Blvd dms Failure Reason Device Type dms Failure Reason Device Type	FDS Uptime Percentage: Manufacturer FDS Uptime Percentage: Manufacturer	





			Report Template Versio	on: 1.2
Device Number	Device Location	Device Type	Manufacturer	
Detour US1 S of 5A NB	US-1 NB S of SR-5A	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ BellevueNB	Williamson Blvd NB at Bellev	vue dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ BellevueSB	Williamson Blvd SB at Bellev	vue dms	FDS	
State	Up/Down Time	Failure Reason	Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ LPGA NB	Williamson Blvd NB at LPGA		FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ LPGA SB	Williamson Blvd SB at LPGA	A dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number Detour Williamson @ SR 40 NB	Device Location Williamson Blvd NB at SR-4	Device Type 0 dms	Manufacturer FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ US 92 NB	Williamson Blvd NB at US-9	2 dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%





Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @ US 92 SB	Williamson Blvd SB at US-92	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @BevilleNB	Williamson Blvd NB at Beville		FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Detour Williamson @BevilleSB	Williamson Blvd SB at Beville	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 @ Enterprise RD WB	I-4 WB at Enterprise Rd	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 @ Ivanhoe EB	I-4 EB at Ivanhoe Blvd	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 @ Kaley WB	I-4 WB at Kaley St	dms	Skyline	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
	Device Location I-4 EB at Michigan St	Device Type dms	Manufacturer DakTronix	
Device Number I-4 @ Michigan EB State				
I-4 @ Michigan EB	I-4 EB at Michigan St	dms		100.0%
I-4 @ Michigan EB <u>State</u>	I-4 EB at Michigan St Up/Down Time	dms Failure Reason	DakTronix Uptime Percentage:	100.0%
I-4 @ Michigan EB	I-4 EB at Michigan St	dms	DakTronix	100.0%
I-4 @ Michigan EB State Device Number	I-4 EB at Michigan St Up/Down Time Device Location	dms Failure Reason Device Type	DakTronix Uptime Percentage: Manufacturer	100.0%





Report Template Version: 1.2

Device Number	Device Location	Device Type	Manufacturer	
-4 E of Ivanhoe EB	I-4 EB E of Ivanhoe Blvd	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of Lake Mary EB	I-4 EB E of Lake Mary Blvd	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of Lake Mary WB	I-4 WB E of Lake Mary Blvd	dms	Vultron	
State	Up/Down Time	Failure Reason		
State	op/bown nine		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-4 E of SR 44 MM 119.3	I-4 WB E of SR-44	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of SR 528 EB	I-4 EB E of SR-528	dms	DakTronix	
State	Up/Down Time	Failure Reason		
online	02/01/2012 09:24:58			
offline	02/01/2012 09:24:58	Device op status was manually change	ed.	
			Uptime Percentage:	94.1%
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of SR 535 EB	I-4 EB E of SR-535	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of SR 535 WB	I-4 WB E of SR-535	dms	Vultron	
State	Up/Down Time	Failure Reason		
	op bown time		Uptime Percentage:	100.0%

Uptime Percentage: 100.0%





				/11. 11.2
Device Number	Device Location	Device Type	Manufacturer	
I-4 E of Saxon Blvd	I-4 EB E of Saxon Blvd	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 EB @ MM 53.7	I-4 EB at MM 54	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 East of Lee Road	I-4 EB E of Lee Rd	dms	DakTronix	
Eastbound				
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 East of SR 434 WB	I-4 WB E of SR-434	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 East of SR 46 EB	I-4 EB E of SR-46	dms	Vultron	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 East of SR 46 WB	I-4 WB E of SR-46	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 East of SR 472 WB	I-4 WB E of SR-472	dms	DakTronix	
State	Up/Down Time	Failure Reason		
Sidle			Uptime Percentage:	100.0%
Davis a Noval	Device Les d'			100.070
Device Number I-4 East of SR 532 WB	I-4 WB E of SR-532	Device Type dms	Manufacturer Vultron	
		uno	Valuon	
State	Up/Down Time	Failure Reason		400.001
			Uptime Percentage:	100.0%





Device Numb	er	Device Location	Device Type	Manufacturer	
-4 East of US		I-4 EB E of US-192	dms	MarkIV	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
-4 W of I-95		I-4 EB W of I-95	dms	FDS	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
-4 W of Conro	y WB	I-4 WB W of Conroy Rd	dms	DakTronix	
State	State	Up/Down Time	Failure Reason		
	offline	02/01/2012 09:26:31	Device op status was manually changed	1.	
	online	02/01/2012 09:26:32			
				Uptime Percentage:	100.0%
Device Numb		Device Location	Device Type	Manufacturer	
-4 W of Fairba	anks WB	I-4 WB W of Fairbanks Ave	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
-4 W of John	Young EB	I-4 EB W of John Young Pkw		DakTronix	
	State	Up/Down Time	Failure Reason		
	offline	02/01/2012 09:35:51	Device op status was manually changed	1.	
	online	02/01/2012 09:35:52			
				Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
-4 W of OBT V	NB	I-4 WB W of OBT	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
	offline	02/01/2012 09:27:05	Device op status was manually changed	1.	
	online	02/01/2012 09:27:05		Uptime Percentage:	100.0%
Device Numb	er	Device Location	Device Type	Manufacturer	
-4 W of SR 43		I4 EB W of SR-434	dms	DakTronix	
	0 4 4				
	State	Up/Down Time	Failure Reason	Untime Deventer-	400.00
				Uptime Percentage:	100.0%





Device Number	Device Location	Device Type	Manufacturer	
I-4 W of SR 44	I-4 EB W of SR-44	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 W of SR 536	I-4 WB W of SR-536	dms	MarkIV	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
I-4 W of US-92 Ramp	I-4 EB W of US-92	dms	FDS	
State	Up/Down Time	Failure Reason		
offline	02/01/2012 00:09:45	None		
online	02/01/2012 00:09:43	None		
offline	02/01/2012 00:26:46	None		
online	02/01/2012 00:33:39	None		
offline	02/01/2012 00:33:41	None		
online	02/01/2012 01:55:41	None		
offline	02/01/2012 02:52:51	None		
online	02/01/2012 03:07:40	None		
offline	02/01/2012 04:11:46	None		
online	02/01/2012 04:42:40	None		
offline	02/01/2012 04:58:52	None		
online	02/01/2012 05:25:45	None		
offline	02/01/2012 05:27:52	None		
online	02/01/2012 05:32:40	None		
offline	02/01/2012 06:54:56	None		
online	02/01/2012 07:05:40	None		
offline	02/01/2012 07:07:57	None		
online	02/01/2012 07:12:40			
offline	02/01/2012 08:09:46	None		
online	02/01/2012 08:11:41			
offline	02/01/2012 08:15:46	None		
online	02/01/2012 08:16:40			
offline	02/01/2012 08:23:46	None		
online	02/01/2012 08:25:40			
offline	02/01/2012 08:30:48	None		
online	02/01/2012 08:31:41			
offline	02/01/2012 08:38:46	None		
online	02/01/2012 08:39:40			
offline	02/01/2012 08:40:46	None		
online	02/01/2012 08:41:40			
offline	02/01/2012 08:46:46	None		
online	02/01/2012 08:47:41			
offline	02/01/2012 08:48:52	None		






online	02/01/2012 08:50:40			
offline	02/01/2012 08:53:46	None		
online	02/01/2012 08:54:40			
			Uptime Percentage:	68.2%
Device Number	Device Location	Device Type	Manufacturer	
-4 W of World Dr EB	I-4 EB W of World Dr	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
4 WB @ MM 56.3	I-4 WB at MM 56	dms	DakTronix	
State	Up/Down Time	Failure Reason		
otate	op/bown nine	Tanure Reason	Uptime Percentage:	100.0%
				100.070
Device Number -4 West of Dirksen RD EB	Device Location	Device Type	Manufacturer	
4 West of Dirksen RD EB	I-4 EB W of Dirksen Rd	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-4 West of SR 417 EB	I-4 EB W of SR-417	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location		Manufacturer	
-4 West of SR 436 WB	I-4 WB W of SR-436	Device Type dms	Vultron	
		dino	(and off	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
95 NB @ MM 172	I-95 NB at MM 172	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
95 NB @ MM 174.3	I-95 NB at MM 174	dms	DakTronix	
-				
04-4-	Un/Deurs Times			
State	Up/Down Time	Failure Reason		400.00/
			Uptime Percentage:	100.0%





			Report remplate versit	JII. 1.2
Device Number	Device Location	Device Type	Manufacturer	
I-95 NB @ MM 178.2	I-95 NB at MM 178	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 190.1	I-95 NB at MM 190	dms	DakTronix	
C				
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 193.3	I-95 NB at MM 193	dms	DakTronix	
		une	Darrienk	
State	Up/Down Time	Failure Reason		
otate	op/Down Time	Tanure Reason	Uptime Percentage:	100.0%
Device Number	Device Leastien	Device True	· · · · ·	
Device Number -95 NB @ MM 199.3	Device Location I-95 NB at MM 199	Device Type dms	Manufacturer FDS	
	1-35 ND at MM 193	uns	105	
Chata	Lin /Dauma Tima			
State	Up/Down Time	Failure Reason	Uptime Percentage:	0.0%
				0.0 /0
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 203.6	I-95 NB at MM 203	dms	FDS	
State	Up/Down Time	Failure Reason		0.00/
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 210.8	I-95 NB at MM 211	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 212.9	I-95 NB at MM 213	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 NB @ MM 217.3	I-95 NB at MM 217	dms	DakTronix	
State	Up/Down Time	Failure Reason		
State			Uptime Percentage:	100.0%
			optime i crocinage.	100.070





Device Number	Device Location	Device Type	Manufacturer	
I-95 NB @ MM 222.1	I-95 NB at MM 222	dms	DakTronix	
State	Up/Down Time	Failure Reason		
	· · · · ·		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 229	I-95 NB at MM 229	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 243	I-95 NB at MM 243	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 248.3	I-95 NB at MM 248	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
-95 NB @ MM 254.1	I-95 NB at MM 254	dms	DakTronix	
U				
State	Up/Down Time	Failure Reason		
State	Op/Down nine		Uptime Percentage:	100.0%
Device Number				
	Device Location	Dovice Type	Manufacturor	
	Device Location I-95 NB at MM 259	Device Type dms	Manufacturer FDS	
	Device Location I-95 NB at MM 259	Device Type dms	Manufacturer FDS	
-95 NB @ MM 259	I-95 NB at MM 259	dms		
			FDS	100.0%
I-95 NB @ MM 259 <u>State</u>	I-95 NB at MM 259 Up/Down Time	dms Failure Reason	FDS Uptime Percentage:	100.0%
-95 NB @ MM 259 State Device Number	I-95 NB at MM 259 Up/Down Time Device Location	dms	FDS Uptime Percentage: Manufacturer	100.0%
I-95 NB @ MM 259	I-95 NB at MM 259 Up/Down Time	dms Failure Reason Device Type	FDS Uptime Percentage:	100.0%
-95 NB @ MM 259 <u>State</u> Device Number -95 NB @ MM 266	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266	dms Failure Reason Device Type dms	FDS Uptime Percentage: Manufacturer	100.0%
-95 NB @ MM 259 <u>State</u> Device Number I-95 NB @ MM 266 <u>State</u>	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time	dms Failure Reason Device Type dms Failure Reason	FDS Uptime Percentage: Manufacturer	100.0%
-95 NB @ MM 259 <u>State</u> Device Number -95 NB @ MM 266	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266	dms Failure Reason Device Type dms	FDS Uptime Percentage: Manufacturer	100.0%
-95 NB @ MM 259 <u>State</u> Device Number -95 NB @ MM 266 <u>State</u> offline	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time 02/01/2012 02:00:07	dms Failure Reason Device Type dms Failure Reason	FDS Uptime Percentage: Manufacturer	100.0%
I-95 NB @ MM 259 State Device Number I-95 NB @ MM 266 State offline online	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time 02/01/2012 02:00:07 02/01/2012 02:00:50	dms Failure Reason Device Type dms Failure Reason None	FDS Uptime Percentage: Manufacturer	100.0%
-95 NB @ MM 259 State Device Number -95 NB @ MM 266 State offline online offline offline	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time 02/01/2012 02:00:07 02/01/2012 02:00:50 02/01/2012 02:25:44	dms Failure Reason Device Type dms Failure Reason None	FDS Uptime Percentage: Manufacturer	100.0%
I-95 NB @ MM 259 State Device Number I-95 NB @ MM 266 State offline online offline online online	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time 02/01/2012 02:00:07 02/01/2012 02:00:50 02/01/2012 02:25:44 02/01/2012 02:27:41	dms Failure Reason Device Type dms Failure Reason None None None	FDS Uptime Percentage: Manufacturer	100.0%
I-95 NB @ MM 259 State Device Number I-95 NB @ MM 266 State offline online offline online offline offline	I-95 NB at MM 259 Up/Down Time Device Location I-95 NB at MM 266 Up/Down Time 02/01/2012 02:00:07 02/01/2012 02:00:50 02/01/2012 02:25:44 02/01/2012 02:27:41 02/01/2012 02:31:47	dms Failure Reason Device Type dms Failure Reason None None None	FDS Uptime Percentage: Manufacturer	100.0%

OF FLORID TO THE OF THE O	DMS Report		SUNGUIDE Florida's Intelligent Transportation Sys	
offline	02/01/2012 06:26:43	None	Report Template Versio	on: 1.2
online	02/01/2012 08:00:46	NUIE	Uptime Percentage:	83.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 NB @ MM 270.4	I-95 NB at MM 270	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 174	I-95 SB at MM 174	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 178.2	I-95 SB at MM 178	dms	DakTronix	
State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
				100.070
Device Number	Device Location I-95 SB at MM 182	Device Type	Manufacturer DakTronix	
I-95 SB @ MM 182	1-95 SB at MIN 162	dms	Daktionix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 184.9	I-95 SB at MM 185	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 196.7	I-95 SB at MM 197	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 203.5	I-95 SB at MM 204	dms	FDS	_
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%





			Report remplate version	/11. 11.2
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 206	I-95 SB at MM 206	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 212.9	I-95 SB at MM 213	dms	DakTronix	
0				
State				
State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
				100.0 //
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 217.2	I-95 SB at MM 217	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 222.3	I-95 SB at MM 222	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 226.7	I-95 SB at MM 227	dms	DakTronix	
0				
Chata				
State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
				100.0 %
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 231.7	I-95 SB at MM 232	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 246	I-95 SB at MM 246	dms	DakTronix	
State	Up/Down Time	Failure Reason		
51410			Uptime Percentage:	100.0%
Davias Number	Device Leastien		· · ·	
Device Number I-95 SB @ MM 251.6	Device Location I-95 SB at MM 252	Device Type dms	Manufacturer DakTronix	
		uno	Burroma	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%





			Report remplate version	JII. 1.2
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 257.5	I-95 SB at MM 258	dms	DakTronix	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 262.5	I-95 SB at MM 263	dms	FDS	
State	Up/Down Time	Failure Reason		
offline	02/01/2012 08:30:48	None		
online	02/01/2012 08:31:45			
offline	02/01/2012 08:52:48	None		
online	02/01/2012 08:53:49			
			Uptime Percentage:	99.6%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 267	I-95 SB at MM 267	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 269	I-95 SB at MM 269	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 275	I-95 SB at MM 275	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
I-95 SB @ MM 298	I-95 SB at MM 298	dms	FDS	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	_
OC-CFP/Seaharbor	Central FL Pkwy WB at Se	a Hbr dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%





				Report Template Versio	/11. 1.2
Device Numbe		Device Location	Device Type	Manufacturer	
C-JYP/Public	Works	JYP NB at Public Works	dms	Vultron	
	State	Up/Down Time	Failure Reason		
	offline	02/01/2012 03:09:40	None		
	online	02/01/2012 03:09:42			
				Uptime Percentage:	99.9%
Device Number		Device Location	Device Type	Manufacturer	
OC-LeeRd/King	gswood	Lee Rd NB at Kingswood Dr	dms	Vultron	
	State	Up/Down Time	Failure Reason		
	offline	02/01/2012 08:05:03	None		
	online	02/01/2012 08:05:05			
	offline	02/01/2012 08:11:01	None		
	online	02/01/2012 08:37:41			
				Uptime Percentage:	95.5%
Device Numbe	er	Device Location	Device Type	Manufacturer	
OC-OBT/26th		OBT SB at 26th St	dms	Vultron	
	04-4-				
	State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
					100.078
Device Number	er	Device Location	Device Type	Manufacturer	
OC-OBT/43rd		OBT NB at 43rd St	dms	Vultron	
	State	Up/Down Time	Failure Reason		
	State	Op/Down Time	Failule Reason	Uptime Percentage:	100.0%
Device Numbe	or	Device Location	Device Type	Manufacturer	
OC-Sand Lk Ro		Sand Lake Rd EB at Dr Philli		Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numbe	er	Device Location	Device Type	Manufacturer	
	d/Universal Blvd	Sand Lake Rd EB at Univers		Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Numbe	er	Device Location	Device Type	Manufacturer	
Port Sign 1		SR-528 EB at MM 52	dms	DakTronix	
	-	··· · - · -·			
	State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
				optime Percentage:	100.0%





Report Template Version: 1.2

Device Numb	ber	Device Location	Device Type	Manufacturer	
Port Sign 2		SR-528 EB at MM 52	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
		Op/Dom: Time		Uptime Percentage:	100.0%
Device Numb	ber	Device Location	Device Type	Manufacturer	
Port Sign 3		SR-528 EB at MM 52	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.09
Device Numb	ber	Device Location	Device Type	Manufacturer	
Port Sign 4		SR-528 EB at MM 53	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.09
Device Numb	ber	Device Location	Device Type	Manufacturer	
Port Sign 5		SR-528 WB E of Port 1	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.09
Device Numb	ber	Device Location	Device Type	Manufacturer	
Port Sign 6		SR-528 WB E of Port 2	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.09
Device Numb)er	Device Location	Device Type	Manufacturer	
SR 528 EB 1		SR 528	dms	FDS	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Numb	ber	Device Location	Device Type	Manufacturer	
		Device Location SR-528 WB E of I-95	Device Type dms	Manufacturer Vultron	
Device Numb SR 528 East o					
	of I-95 WB	SR-528 WB E of I-95	dms		100.0
	of I-95 WB State	SR-528 WB E of I-95	dms	Vultron	100.0
SR 528 East of Device Numb SR 528 West	of I-95 WB State	SR-528 WB E of I-95 Up/Down Time Device Location	dms Failure Reason Device Type	Vultron Uptime Percentage: Manufacturer	100.0

Page 29 of 34





Dovioe Num	hor	Davias Lasstian	Dovice Type	Manufacturer	
Device Numl Universal 115		Device Location Universal Sign 115	Device Type dms	Manufacturer Vultron	
)	Universal Sign 115	unis	valuon	
	State	Up/Down Time	Failure Reason		
		•		Uptime Percentage:	0.0%
Device Num	ber	Device Location	Device Type	Manufacturer	
Universal Sig	n 101	Universal 101	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Num		Device Location	Device Type	Manufacturer	
Universal Sig	n 102	I-4 at Universal right	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Num	ber	Device Location	Device Type	Manufacturer	
Universal Sig		I-4 at Kirkman Universal Si		Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	100.0%
Device Num	ber	Device Location	Device Type	Manufacturer	
Universal Sig	n 111	Universal Sign 111	dms	DakTronix	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
Device Num	her	Device Location	Device Type	Manufacturer	
Universal Sig		Universal sign 112	dms	Vultron	
-		-			
	State	Up/Down Time	Failure Reason		
		•		Uptime Percentage:	0.0%
Device Num	ber	Device Location	Device Type	Manufacturer	
Universal Sig		Universal Sign 113	dms	Vultron	
	State	Up/Down Time	Failure Reason		
				Uptime Percentage:	0.0%
	ber	Device Location	Device Type	Manufacturer	
Device Num		Universal Sign 114 Top	dms	Vultron	
Device Num Universal Sig	n 114 Top	Universal orgin 114 10p			
	n 114 Top State	Up/Down Time	Failure Reason		





			Report Template Versio	
Device Number	Device Location	Device Type	Manufacturer	
Universal Sign 114 bottom	Universal Sign 114	dms	Vultron	
State	Up/Down Time	Failure Reason		
State	op/down time	Failule Reason	Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Universal Sign 91	Universal Sandlake Rd Lft	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Universal Sign 92	Universal Sign 92	dms	Vultron	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
Universal Sign 93	Universal Sign @ Sand Lk le		Vultron	
State	Up/Down Time	Failure Reason		
State	op/down time	Failule Reason	Uptime Percentage:	0.0%
Device Number	Device Location	Device Type	Manufacturer	
Universal Sign 94	Universal Sign @ Sand Lk ri		Vultron	
State	Up/Down Time	Failure Reason		
	op/Down Time		Uptime Percentage:	100.0%
Device Number	Device Location		Manufacturer	
VSL 01 I-4 W of SR 414	VSL 01 I-4 W of SR 414	Device Type dms	DakTronix	
State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 02 I-4 W of SR 414 EB	VSL 02 I-4 W of SR 414 EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 03 I-4 W of SR 414 WB	VSL 03 I-4 W of SR 414 WB		DakTronix	
State	Up/Down Time	Failure Reason		
	- p: =		Uptime Percentage:	100.0%





			Report remplate version	<i>.</i> 1.2
Device Number	Device Location	Device Type	Manufacturer	
VSL 04 I-4 W of SR 414	4 EB VSL 04 I-4 W of SR 414 EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
State	Op/Down Time		Uptime Percentage:	100.0%
- · · · ·	- · · · <i>.</i>			100.070
Device Number VSL 05 I-4 W of 423 W	B VSL 05 I-4 W of 423 WB	Device Type	Manufacturer DakTronix	
VSL 05 1-4 W 01 425 W	B V3L 05 1-4 W 01 423 WB	dms	Daktronix	
• / /				
State	Up/Down Time	Failure Reason		400.0%
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 06 I-4 W of SR 423	3 EB VSL 06 I-4 W of SR 423 EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
	•		Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 07 I-4 E of Par Ave		dms	DakTronix	
01-1-				
State	Up/Down Time	Failure Reason		400.00/
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 08 I-4 E of Par Ave	EB VSL 08 I-4 E of Par Ave EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 09 I-4 W of Par Av	e WB VSL 09 I-4 W of Par Ave WB		Vultron	
State	Up/Down Time	Failure Reason		
	Op/Down Time		Uptime Percentage:	100.0%
				100.070
Device Number	Device Location	Device Type	Manufacturer	
VSL 10 I-4 W of Par Av	e EB VSL 10 I-4 W of Par Ave EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 11 W of Ivanhoe V	VB VSL 11 W of Ivanhoe WB	dms	DakTronix	
Ctoto	Un/Down Time	Eailura Baacan		
State	Up/Down Time	Failure Reason	Uptime Percentage:	100.0%





Device Number	Device Location	Device Type	Manufacturer	
VSL 12 I-4 W of Ivanhoe	I-4 W of Ivanhoe EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 13 E of Kaley	VSL I-4 E of Kaley	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 14 I-4 E of Kaley St EB	VSL 14 I-4 E of Kaley St EB	dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 15 I-4 E of Westmoreland W	VSL 15 I-4 E of Westmoreland	I W dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 16 I-4 E of Westmoreland E	VSL 16 I-4 E of Westmoreland	IE dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 17 I-4 W of Rio Grande WB	VSL 17 I-4 W of Rio Grande V	VB dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 18 I-4 W of Rio Grande EB	VSL 18 I-4 W of Rio Grande E	B dms	DakTronix	
State	Up/Down Time	Failure Reason		
			Uptime Percentage:	100.0%





Report Template Version: 1.2

Device Number	Device Location	Device Type	Manufacturer	
VSL 19 I-4 W of Rio Grande WB	VSL 19 I-4 W of Rio Grande WB	dms	DakTronix	
State	Up/Down Time Failu	re Reason		400.0%
			Uptime Percentage:	100.0%
Device Number	Device Location	Device Type	Manufacturer	
VSL 20 I-4 W of Rio Grande EB	VSL 20 I-4 W of Rio Grande EB	dms	DakTronix	
State	Up/Down Time Failu	re Reason		

Uptime Percentage: 100.0%