

WWD Report



Report Template Version 1.0

Created On: 12/06/2016 10:59:14

Center: District 7

Filter Parameters Selected:

Device Number	Device Location	Device Type	Manufacturer
-275 43.8 SB WWD	Wrong Way NB from SB Downto	own wrongWayDevice	Wavetronix
	Ramps		
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 0.0%
Device Number	Device Location	Device Type	Manufacturer
-275 45.0 SB WWD	Wrong Way NB from SB Floribra	aska wrongWayDevice	Wavetronix
	Ave Ramp		
<u>State</u>	Up/Down Time Failu		
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
-275 45.5 NB WWD	Wrong Way SB from NB MLK B		Wavetronix
	Ramp	g ,	
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
I-275 45.8 SB WWD	Wrong Way NB from SB MLK B		Wavetronix
	Ramp	-	
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 0.0%
Device Number	Device Location	Device Type	Manufacturer
I-275 46.5 NB WWD	Wrong Way SB from NB	wrongWayDevice	Wavetronix
	Hillsborough Ave Ramp	-	
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
I-275 46.8 SB WWD	Wrong Way NB from SB	wrongWayDevice	Wavetronix
	Hillsborough Ave Ramp	-	
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
-275 47.5 NB WWD	Wrong Way SB from NB Sligh A	ve wrongWayDevice	Wavetronix
	Ramp		
State	Up/Down Time Failu	ire Reason	
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
-275 47.8 SB WWD	Wrong Way NB from SB Sligh A		Wavetronix
	Ramp	- *	
State	Up/Down Time Failu	ıre Reason	



WWD Report



Report Template Version 1.0

Created On: 12/06/2016 10:59:14

Center: District 7

Filter Parameters Selected:

ocatio	n		Device	Туре	Manufact	turer
		IB Bird Sti	eet wrong\		Wavetron	
-			_	•		
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
.ocatio			Device		Manufact	
/ay SB	from N	IB Busch	Blvd wrong\	VayDevice	Wavetron	ix
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
		SB Busch	Blvd wrong\		Wavetron	ix
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
/ay SB	from N	IB Fowler	Ave wrong\	VayDevice	Wavetron	ix
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
/ay NB	from S	SB Fowler	Ave wrong\	VayDevice	Wavetron	ix
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
/ay NB ip	from S	SB Fletche	r wrong\	VayDevice	Wavetron	ix
wn Tii	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
/ay SB	from N	IB Bearss	Ave wrong\	VayDevice	Wavetron	ix
wn Ti	me	Failu	re Reason			
					Uptin	ne Percentage: 100.0%
ocatio	n		Device	Туре	Manufact	turer
Wrong Way NB from SB Bearss Ave wrongWayDevice Ramp		Wavetron				
wn Tii	mo	Failu	re Reason			



WWD Report



Report Template Version 1.0

Created On: 12/06/2016 10:59:14

Center: District 7

Filter Parameters Selected:

Device Number	Device Location	Device Type	Manufacturer
-275 54.1 NB WWD	Wrong Way NB in SB flow	wrongWayDevice	Wavetronix
State	Up/Down Time Faile	ure Reason	
			Uptime Percentage: 0.0%
Device Number	Device Location	Device Type	Manufacturer
-275 54.1 SB WWD	Wrong Way SB in NB flow	wrongWayDevice	Wavetronix
State	Up/Down Time Faile	ure Reason	
			Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
-4 0.2 WB WWD	Wrong Way EB in WB flow	wrongWayDevice	Wavetronix
State	Up/Down Time Faile	ure Reason	
	-		Uptime Percentage: 100.0%
Device Number	Device Location	Device Type	Manufacturer
-4 0.3 EB WWD	Wrong Way WB in EB flow	wrongWayDevice	Wavetronix
State	Up/Down Time Faile	ure Reason	